



**Free Installation**

**Free Seat Stop**

**Attention**

## **Cessna Aircraft Owners**

On December 17, 2007 the following Owner Advisory message was sent to applicable owners of record in SEB07-5R1A.

Dear Cessna Owner:

This Owner Advisory is to inform you that Service Bulletin SEB07-5 Revision 1: Pilot and Copilot Secondary Seat Stop Installation has been issued to announce that Service Kits are available to install a new design secondary seat stop for the pilot and copilot seats.

The secondary seat stop is designed to assist in providing an additional margin of safety by limiting the aft travel of the seat in the event the primary latch pin is not properly engaged in the seat rail/track. In certain instances, seat slippage could result in some pilots not being able to reach all the controls and/or subsequently losing control of the airplane.

Compliance is mandatory for the pilot seat: the secondary seat stop installation shall be accomplished within the next 400 hours of operation or 24 months, whichever occurs first. Compliance is recommended for the copilot seat: the secondary seat stop installation should be accomplished within the next 400 hours of operation or 24 months, whichever occurs first.

**NOTE:** This Service Bulletin supersedes Service Bulletin SEB89-2: Pilot Seat Secondary Stop Installation (all revisions).

Compliance with SEB07-5 Revision 1 is not required if in compliance with the Original Issue of SEB07-5.

The information contained in the referenced Cessna Service Bulletin shall be considered an amendment to the Cessna Manufacturer's Service/Maintenance Manual or Instructions for continued airworthiness, and must be accomplished for ongoing airworthiness compliance in accordance with 14 CFR Part 43.13.

Applicable Service Kit parts credit and applicable labor allowance credit, as listed in the Man-Hours section of Service Bulletin SEB07-5, will be provided per airplane to install Service Kits SK195-11 and SK210-174A: Pilot Secondary Seat Stop Installation.

To receive credit, the work must be completed and a Warranty Claim submitted by a Cessna Multi-engine Service Station within 30 calendar days of Service Bulletin compliance before the credit expiration dates shown below.

Domestic . . . . . December 17, 2009  
International . . . . . December 17, 2009

**Contact us "TODAY" at 1-877-438-2359, [cessnaparts@evasair.com](mailto:cessnaparts@evasair.com)**

**Exploits Valley Air Services Ltd**

**"Your Atlantic Canada Authorized Cessna Service Facility"**