



Attention Cessna Aircraft Owners

On June 15, 2011 the following Owner Advisory message was sent to applicable owners of record to extend SEB07-5R2A.

Dear Cessna Owner,

This Owner Advisory is to inform you that Service Bulletin SEB07-5 Revision 2: Pilot and Copilot Secondary Seat Stop Installation have been issued to announce that Service Kits are available to install a new design secondary seat stop for the pilot and copilot seats.

The Secondary Seat Stop is an additional device installed on the pilot and copilot seat that assists in preventing uncommanded rearward movement of the seat. It is designed to assist in providing an additional margin of safety by limiting the aft travel of the seat should the primary seat latch pin(s) not be properly engaged in the seat rail/track. In certain instances, seat slippage could result in some pilots not being able to reach all the controls and/or subsequently losing control of the operator. If operation of the seat stop is not transparent the airplane requires maintenance to correct the malfunction of the seat stop mechanism.

Compliance is mandatory for the pilot seat: the secondary seat stop installation shall be accomplished within the next 400 hours of operation or 24 months, whichever occurs first.

Compliance is recommended for the copilot seat: the secondary seat stop installation should be accomplished within the next 400 hours of operation or 24 months, whichever occurs first.

NOTE: This service Bulletin supersedes Service Bulletin SEB89-2: Pilot Secondary Stop Installation (all revisions)

Compliance with SEB07-5 Revision 2 is not required if in compliance with the Original Issue or Revision 1 of SEB07-5.

The information contained in the referenced Cessna Service Bulletin shall be considered an amendment to the Cessna Manufacturer's Service/Maintenance Manual or Instructions for continued airworthiness, and must be accomplished for ongoing airworthiness compliance in accordance with 14 CFR Part 43.13.

Domestic.....June 15th, 2012
International.....June 15th, 2012

Contact us TODAY at 1-877-438-2359 or at cessnaparts@evasair.com

Exploits Valley Air Services Ltd.
Your Atlantic Canada Authorized Cessna Service/Pilot Center
“Where Great Service Keeps You Flying!”